

MassWorks Version 2.XX known issues

(Version 2.0.2.0)

Case 350: m/z values of Calibrated data file may change when its calibration file is opened

Symptom: When a calibration file is open in calibration mode, accurate mass values may be slightly different in some cases then when a calibration file is not loaded.

Notes: This bug has been logged an is being investigated

Solution: Clear the calibration file from memory before reviewing accurate mass values in Analysis Mode. This can be done by simply clicking on the “New Calibration” toolbar button in Calibration

Mode ().